Oil Field Environmental Incident Summary

Responsible Party: Torrent Energy Services

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: CHARGING EAGLE 10-14-11-2H3

Field Name: TWIN BUTTES Well File #: 25293

Date Incident: 11/23/2015 Time Incident: 11:00 Facility ID Number:

County: DUNN Twp: 147 Rng: 92 Sec: 14 Qtr: NW SE

Location Description:

Submitted By: Jake Wilson Received By:

Contact Person: Jake Wilson

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 1 Barrels

Description of Other Released Contaminant:

Ethylene Glycol (80% Glycol, 20% Water)

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:To be determined

Areal Extent:

Potential Environmental Impacts:

To be determined

Action Taken or Planned:

Torrent operator replaced both nipples on each end going into the ball valves on the EG line. Containment may have to be expanded on the NGL skid..

Wastes Disposal Location:

Agencies Involved: MHA, BIA, TAT, NDIC

Updates

Date: 11/23/2015 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.